

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 6

1445 ROSS AVENUE, SUITE 1200 DALLAS, TEXAS 75202-2733

March 16, 2005

REPLY TO: 6EN-WC

Mr. John Ramos Ruidoso-Ruidoso Downs WWTP 313 Creemeadows Drive Ruidoso, NM 88345

MAR 2 1 7 . 5

Re: NPDES Permit No. NM0029165

Dear Mr. Ramos:

The above referenced facility is in violation of the above referenced permit. The Number of Excursions (No Ex) reported for the monitoring period are indicated in parenthesis.

<u>Date</u>	<u>Outfall</u>	<u>Parameter</u>	<u>Violation</u>	Limit (No Ex)
1/05	001A	T.Phosphorus,		
1/05	001A	30-day avg. T.Phosphorus,	24.7 lbs/dy	2.2 lbs/dy
1/6/05	001A	30-day avg. T.Phosphorus,	2.04 mg/l	0.1 mg/l
		Daily max.	2.04 mg/l	0.15 mg/l (1)

For further information, see the web pages listed below.

The Clean Water Act is on the web page: http://www.epa.gov/region6/6en/w/cwa.htm

The Discharge Monitoring Report is on the web page: http://www.epa.gov/region6/6en/w/dmr.htm

Click on the underscored words, "NPDES Reporting Handbook" for a sample Noncompliance Compliance Report form for your use.

Your facility should take whatever remedial action is necessary to prevent the recurrence of the violations noted above.

We have placed in your file a list of the above violations, as well as any corrective measures you have reported. In the event of future violations, we will use this information in determining what appropriate actions to take.

If you have any questions, please contact me at the above address or telephone (214) 665-7491.

Sincerely yours,

Waudelle Strickley (6EN-WC) Environmental Specialist NPDES Compliance Section strickley.waudelle@epa.gov

(214) 665-7491

Fax: (214) 665-2168

cc: Marcy Leavitt

Surface Water Bureau

New Mexico Environment Department